



# Factory Restore F9

**NOTE: ALL EXISTING DATA WILL BE LOST, PLEASE BACKUP ANY POS SOFTWARE DATA BEFORE PREFORMING SYSTEM RESTORE.**


1) WHILE UNIT IS BOOTING, **PRESS F9** REPEATEDLY




2) AT WINDOWS BOOT MANAGER, **PRESS ENTER**




3) **PRESS 1** FOR RESTORE TO C: AND THEN **PRESS ENTER**



4) THE RESTORE PROCESS IS IN PROGRESS, PLEASE WAIT



5) **PRESS ANY KEY ONCE YOU SEE THE OPERATION HAS COMPLETED SUCESSFULLY.**



6) **PRESS 3** AND THEN **PRESS ENTER**, THE UNIT WILL NOW REBOOT

7) THE UNIT WILL NOW BOOT IN TO WINDOWS NORMALLY.