

Model 4210 to LSC 2000 I/O Cable Installation Instructions

14-3890-000

FOR INTERFACE CABLE 14-3257-000

- 1) Remove the GC I/O cable (if already connected) from the rear panel of the LSC 2000.
- 2) Connect the 25 pin connector of the '4210 to LSC 2000' cable to the GC I/O connection on the back of the LSC 2000 panel.
- 3) Connect the LSC 2000 GC I/O cable to the piggy back connection on the '4210 to LSC 2000' cable.
- 4) Connect the 5-wire connector on the other end of the cable to the output connector on the 4210 labeled "CONCENTRATOR".
- 5) Make sure power to the LSC 2000 is off.
- 6) Remove the right side panel.
- 7) Unplug the purge and vent valves for the front panel board.
- 8) Plug in the two piggy back connectors from the Prepurge Retrofit Assembly.
- 9) Plug the valves into the back of the piggy back connectors.
- 10) Put the side panel back on, with the cable coming out of the unit between the rear and side panels.
- 11) Plug the 2 pin prepurge connector from the Retrofit Assembly into the prepurge connection on the rear of the Model 4210.

The LSC 2000 will advance the Model 4210 to prepurge and the Model 4210 will signal the LSC 2000 to advance to purge when the Model 4210 is ready to purge.

022090