



Removing the tray arm assembly. See next page.

Figure 1030-8



Tray arm assembly (18596-60855)

Figure 1030-9



Replaced by Matching Halves Kit 18596-60945:

- 1 Left arm half 18596-40045
- 2 Right arm half 18596-40055