
Transport Assembly

Table 10

Transport Assembly

Item	Description	HP Part Number
1	Transport Assembly (complete)	G1313-60009
2	Finger Caps (pack of 15)	5063-6506
3	Gripper Assembly	G1313-60010
4	Screw for Motor (M3 × 0.5)	0515-0886
	Washer for Motor Screws	3050-0891
5	Motor Assembly	G1313-89700
	Belt for X and Z axes (not shown)	1500-1017
	Belt for theta (gripper) axis (not shown)	1500-1018

Figure 27 **Transport Assembly**

