

# NeverStrip Rubber Seal made this running track better than new.



**Before NeverStrip**



**Before and After  
NeverStrip Treatment**



**One Year After  
NeverStrip Treatment**

---

**During the 2020 Pandemic** a Chicago suburban park district maintenance team decided to perform a deep restorative clean of their rubber running track.

**It was likely the first** restorative cleaning since installation years earlier.

**The cleaning took multiple passes** with NeverStrip Deep Clean cleaner and 175 rpm floor machines with green scrubbing pads. After the floor was thoroughly cleaned and dried, three applications of NeverStrip Rubber Seal were applied to the track.

**The results were stunning.** The floor looked better than new with an attractive satin finish. Runners and walkers using the track praise the traction of the surface with the 21st Century Micron sealer. Park District Members think they are running on a new track. The rubber surface is now easier to clean and keep clean.

---

Quote from Maintenance Team Member:

**“Rubber Seal has now made it easier to clean the rubber track.  
Soil and marks were difficult to remove from the rubber surface.  
Soil and marks are now easy to remove.”**



21st Century Floor Care Technology™

For more information, visit [NeverStrip.com](https://NeverStrip.com) or contact Dave Beedie  
[david.beedie@neverstrip.com](mailto:david.beedie@neverstrip.com) • 630-330-1010